


Notes: Voltage Feedback regulation with hysteresis causes inverter osc to switch on/off when 330V reached.
 B101/B102 cause hysteresis and set level.
 Provided enough current is available this makes output independent of battery state.

Connectors shown
 External Front View
 = Metal Frame and Flash Shoe Frame

This diagram for non-commercial educational purposes.
 May not be resold.
 I retain copyright. T.Hughes
 TimHughes@ieee.org

Title OLYMPUS BOUNCE GRIP 2 (house code: MPPG-B)		
Size A	Document Number (C) T.Hughes 2000/2001/2006	Rev 1.01
Date: Tuesday, September 26, 2006	Sheet 1	of 1